



## Weld and Shim Plate Specifications

314 Axminister Dr.  
Fenton, MO 63026

(866) 206-8792

What's the difference?

Weld plates are unplated, raw steel that can be welded to the bottom of your equipment and painted so you can bolt corresponding plate casters to them.

Shim plates are zinc plated spacers and should not be used for welding.




A14ZZ06YY



A14ZZ06SP


Overall Size	Bolt Hole Pattern	Thickness	Unplated Part Number	Zinc Plated Part Number
2-3/8" x 3-5/8"	1-3/4" x 2-7/8" Slotted to 1-3/4" x 3"	.215"	A14ZZ06YY	A14ZZ06SP
3-1/8" x 4-1/8"	1-3/4" x 2-15/16" Slotted to 2-3/8" x 3-3/8"	.215"	N/A	A14ZZ11SP
4" x 4-1/2"	2-5/8" x 3-5/8" Slotted to 3" x 3"	.175"	A28ZZ17YY	A28ZZ17SP



A14ZZ11SP



A14ZZ17YY



A14ZZ17SP